

Oil Field Environmental Incident Summary

Incident: 20150502131853 **Date/Time of Notice:** 05/02/2015 13:18

Responsible Party: OXY USA INC.

Well Operator: OXY USA INC.

Well Name: CABERNET SWD 1

Field Name: CABERNET

Well File #: 90174

Date Incident: 5/1/2015 **Time Incident:** 13:00

Facility ID Number:

County: DUNN

Twp: 144

Rng: 97

Sec: 34

Qtr:

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Person: Robyn Espinoza
5 GREENWAY PLAZA STE 110
HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	barrels	10	barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Contaminated surface material

Areal Extent:

Potential Environmental Impacts:

Contaminated surface material

Action Taken or Planned:

An isolation valve was installed to prevent any further release, a vac truck was dispatched to recover all standing liquids. An investigation is underway to determine the root cause of the leak, repairs will be made to the line as necessary.

Wastes Disposal Location:**Agencies Involved:****Updates**

Date: 5/4/2015 **Status:** Reviewed - Assigned to Other Agency**Author:** Stockdill, Scott**Updated Oil Volume:****Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

According to the incident summary, this incident remained on location. NDIC retains oversight.